

(DAVVY2.DAVVY) 19059

DAVVY TWO DEPARTURE (OBSTACLE) (RNAV)

AL-9146 (FAA)

LAKE COUNTY (LXV)
LEADVILLE, COLORADO

ASOS
118.375
DENVER CENTER
119.85 363.15
UNICOM
122.8 (CTAF)

△ DAVVY

346°
(16)

◇ OLOWI

NOTE: GPS required.
NOTE: RNAV 1.
NOTE: RADAR required.

TAKEOFF MINIMUMS

Rwy 16: NA, ATC.
Rwy 34: Standard with minimum climb of 337' per NM to 13200.

TAKEOFF OBSTACLE NOTES

Rwy 34: Pole 10' from DER, 26' left of centerline, 2' AGL/9932' MSL.
Trees beginning 18' from DER, 462' right of centerline, up to 9949' MSL.

NOTE: Chart not to scale.

DEPARTURE ROUTE DESCRIPTION

TAKEOFF RUNWAY 34: Climb direct OLOWI, then on track 346° to DAVVY, then on assigned route, maintain 16000.

SW-1, 07 OCT 2021 to 04 NOV 2021

SW-1, 07 OCT 2021 to 04 NOV 2021

DAVVY TWO DEPARTURE (OBSTACLE) (RNAV)
(DAVVY2.DAVVY) 28FEB19

LEADVILLE, COLORADO
LAKE COUNTY (LXV)